


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
|-----------|-----------|----------------|------------------|-------------|------------------|--------------------|--------------|
| S1028-213 | Smoke | 8/10/2009 | ADS/TM | S19KK_025MH | Dry | Yes | 401.17 |



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
|-----------|-----------|----------------|------------------|-------------|------------------|--------------------|--------------|
| S1028-213 | Smoke | 8/10/2009 | ADS/TM | S19KK_025MH | Dry | Yes | 401.17 |

Isolated Pipes

| Pipe ID | Upstream MH | Downstream MH | Length (ft) | Diameter (In) |
|-------------|-------------|---------------|-------------|---------------|
| S19KK_018G1 | S19KK_018MH | S19KK_025MH | 77.533 | 8 |
| S19KK_025G1 | S19KK_025MH | S19KK_022MH | 142.896 | 8 |
| S19KK_063G1 | S19KK_063DE | S19KK_025MH | 180.739 | 8 |

Observations & Photos

Obs_ID S1028-213-OB01
Address 1923 Walbrook Ave
Status Private
Source Cleanout

Location Paved concrete
Nearest MH S19KK_025MH

Comments Smoke from above-grade cleanout in paved concrete in back yard. 1923 Walbrook Ave.



Picture \S1028-213-OB01-P01.jpg

Comments Back of house, 1923 Walbrook Ave.

Obs_ID S1028-213-OB02
Address 1918 Herbert St
Status Private
Source Cleanout

Location Paved concrete
Nearest MH S19KK_025MH

Comments Smoke from cleanout in paved concrete in back yard. 1918 Herbert St.



Picture \S1028-213-OB02-P01.jpg

Comments Back of house, 1918 Herbert St.